


#7C-17508 2 Speed Windshield Wiper Motor for 1948-52 Ford Pickup Truck


NOTICE: The driver's side lower dash to firewall support brace must be bent towards the dash (away from the firewall) in order for the left side wiper pivot to clear and function properly.

NOTICE: On trucks with 2 braces, the lower dash panel to cowl braces must be removed and replaced with these 2 replacement brackets.




WIPER STOP ADJUSTMENT.

If the windshield wipers in stop position need further adjustment, remove the motor drive arm from the shaft, rotate the arm slightly clockwise or counterclockwise to achieve the correct position then reinstall the motor drive arm.



WIRE CONNECTIONS FROM MOTOR TO SWITCH AND SWITCH TO POWER



ALL PARTS ONLINE
www.dennis-carpenter.com

ORDER A PARTS CATALOG TOLL FREE
1-800-476-9653

1932-48 Ford/Merc	1965-72 Galaxie/Full size	1967-72 Ford Pickup
1949-51 Ford/Merc	1960-70 Falcon/Ranchero	1973-79 Ford Pickup
1952-56 Ford/Merc	1962-79 Fairlane/Torino	1980-89 Pickup/Bronco
1957-59 Ford/Merc/Edsel	1932-47 Ford Pickup	1966-79 Ford Bronco
1955-66 Thunderbird	1948-56 Ford Pickup	1939-54 Ford Tractor
1960-64 Galaxie/Full size	1957-66 Pickup/Econoline	1936-65 Cushman Scooter
1965-93 Mustang		

NOTICE: CHECK THE FUSE

If after installation your electric wiper motor does not run, make sure that the inline fuse has not blown.