



FORD PERFORMANCE

## M-6766-A50 2015-2016 Mustang Oil Separator

NO PART OF THIS DOCUMENT MAY BE REPRODUCED WITHOUT PRIOR AGREEMENT AND WRITTEN PERMISSION OF FORD PERFORMANCE PARTS


Please visit [www.fordracingparts.com](http://www.fordracingparts.com) for the most current instruction and warranty information.

**PLEASE READ ALL OF THE FOLLOWING INSTRUCTIONS CAREFULLY PRIOR TO INSTALLATION. AT ANY TIME YOU DO NOT UNDERSTAND THE INSTRUCTIONS, PLEASE CALL THE FORD PERFORMANCE TECHLINE AT 1-800-367-3788**


### Kit contents:

- 1 - Oil separator
- 2 - Hoses
- 2 - Push pins

### Step 1. Remove breather hose labeled #1



E185505



E151707

Factory Ford shop manuals are available from Helm Publications, 1-800-782-4356




**FORD PERFORMANCE**

## M-6766-A50 2015-2016 Mustang Oil Separator

NO PART OF THIS DOCUMENT MAY BE REPRODUCED WITHOUT PRIOR AGREEMENT AND WRITTEN PERMISSION OF FORD PERFORMANCE PARTS

**Step 2. Remove electrical harness from valve cover. (on GT350 installations additional adjustments of the electrical harness is necessary to clear oil separator)**

**Step 3. Install oil separator using the 2 push pins provided**



Factory Ford shop manuals are available from Helm Publications, 1-800-782-4356




**FORD PERFORMANCE**

## M-6766-A50 2015-2016 Mustang Oil Separator

NO PART OF THIS DOCUMENT MAY BE REPRODUCED WITHOUT PRIOR AGREEMENT AND WRITTEN PERMISSION OF FORD PERFORMANCE PARTS

**Step 4. Reinstall electrical harness onto oil separator bracket.**

**Step 5. Install 2 breather hoses**



Maintenance is based on the type of driving the vehicle is subjected to.

Track type driving will require more frequent checks for accumulation of oil in the separator.

Remove separator and tilt so to empty oil out from the **lower** fitting. Do not empty from upper fitting!

If removal of the top cover is required, when reinstalling torque socket head screws to 4.5 to 5 Nm.

Factory Ford shop manuals are available from Helm Publications, 1-800-782-4356